STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING		(X3) DATE SURVEY COMPLETED	
17534			B. WING		11/21/2013		
NAME OF PROVIDER OR SUPPLIER			STREET ADD	RESS, CITY, STA	TE, ZIP CODE		
ALDERSGATE VILLAGE			3220 SW AI TOPEKA, K	LBRIGHT DR S 66614			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORREC' (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPR DEFICIENCY)	TION SHOULD BE THE APPROPRIATE	
S 000	The following citations represent the findings of a Health Resurvey.			S 000			
S1166 SS=E				S1166			
	the corridor door at the activate an electronic each required staff mespecific resident or robeen placed; and (iv) light and a repeating workroom or area, of workroom, and medicactivate the portable of the state o	flashing light adjacent to site of the emergency portable device worn be ember, identifying the som from which the call produce a rapidly flash audible signal in the nuclean workroom, soiled cation preparation roomelectronic device worn ember with an audible	y or has hing irses as or by				
	(C) The administrator shall implement a policy to ensure that all calls activated from an emergency location receive a high-priority response from staff.						

If deficiencies are cited, an approved plan of correction is requisite to continued program participation. LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

STATE FORM 021199 W9WZ11 If continuation sheet 1 of 4

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED			
17534		175340		B. WING	B. WING		11/21/2013			
NAME OF PROVIDER OR SUPPLIER ALDERSGATE VILLAGE			3220 SW A	STREET ADDRESS, CITY, STATE, ZIP CODE 3220 SW ALBRIGHT DR TOPEKA, KS 66614						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FUL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A: CROSS-REFERENCED TO DEFICIE	CTION SHOULD BE O THE APPROPRIATE	(X5) COMPLETE DATE			
S1166	Continued From Page 1 This Requirement is not met as evidenced by: K.A.R. 26-40-303(h)(1)(B)(1V) K.A.R. 26-40-303(h)(1)(B) The facility identified a census of 186 residents Based on observation and interview the facility failed to provide an audible call signal in 2 soile and 1 clean utility rooms on 1 of 8 units for 1 of days onsite of the survey and failed to provide emergency call system in resident showers for of 8 units for 4 of 4 days onsite of the survey. Findings included: On 11-12-13 at 9:07 A.M. during the initial to observation revealed the call light did not soun 2 soiled utility rooms and in one clean utility room On 11-12-13 at 9:35 A.M. housekeeping/maintenance staff Z went into the soiled utility room on Eastminster and stated when a resident's call light came on, then it sho sound in the soiled and clean utility rooms. The resident call light was not audible in the soiled utility room. The facility failed to ensure there was an audib call system in the soiled/clean utility rooms on the soiled utility rooms on the soiled/clean utility rooms on the soiled/cl		nts. lity biled of 4 de for 1 y. tour, und in room. the d should The ed	S1166	DEFICIE	NCY)				
	resident #276 's bath	7 P.M. observation revolution revolution with a shower. Thergency call system with	he							
On 11-13-13 at 10:25 P.M. observation revealed resident #277's bathroom with a shower. The shower lacked an emergency call system within reach.		he								

If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATE FORM 021199 W9WZ11 If continuation sheet 2 of 4

		(X1) PROVIDER/SUPPLIER/C IDENTIFICATION NUMB		(X2) MULTIPLE CONSTRUCTION A. BUILDING		(X3) DATE SURVEY COMPLETED			
175340				B. WING		11/21/2013			
NAME OF PROVIDER OR SUPPLIER ALDERSGATE VILLAGE			STREET ADDRESS, CITY, STATE, ZIP CODE 3220 SW ALBRIGHT DR TOPEKA, KS 66614						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OI (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	CTION SHOULD BE COMPLETE O THE APPROPRIATE DATE			
S1166	On 11-19-13 at approximately 10:30 A.M. during the environmental tour, interview with housekeeping/maintenance staff AA stated staff stayed with the residents while they showered and			S1166					
	The facility failed to system by the show	rovide an emergency call							
S1170 SS=D	S1170 SS=D 26-40-303 (h)(1)(G)(i)(ii)(iii) P E - Nursing facility support system (G) If a nursing facility uses a wireless system to meet the requirements of paragraphs (h)(1)(A) through (E), all of the following additional requirements shall be met:		m to	S1170					
	(i) The nursing facility shall be equipped with a system that records activated calls. (ii) A signal unanswered for a designated period of time, but not more than every three minutes, shall repeat and also be sent to another workstation or to staff that were not designated to receive the original call. (iii) Each wireless system shall utilize radio frequencies that do not interfere with or disrupt pacemakers, defibrillators, and any other								
	medical equipment a initiated from the matrix. This Requirement is The facility had a ceupon observation are to ensure the wireless.	and that receive only signufacturer 's system. s not met as evidenced the sus of 186 residents. In the interviews the facility is call system functioned sided on Westminster for	oy: Based failed d for						

If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATE FORM 021199 W9WZ11 If continuation sheet 3 of 4

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 175340		` '		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
						COMPLE		
			B. WING		11/2	11/21/2013		
NAME OF PROVIDER OR SUPPLIER STREET A				RESS, CITY, STA	ATE, ZIP CODE	-		
ALDERSG	ATE VILLAGE		3220 SW A TOPEKA, K	LBRIGHT DR (S 66614				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF ((EACH CORRECTIVE ACTI CROSS-REFERENCED TO TI DEFICIENC	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETE DATE	
S1170	Continued From Page 3			S1170				
	Findings included: On 11/13/13 at approximately 9:35 A.M. observation revealed when residents' call lights were activated there was a 2 and a half minute delay before the call signal reached a staff's beeper to alert them a resident activated his/her call light. Observation also revealed not all of the call light signals on the hall activated the staff beeper. On 11/13/13 at approximately 9:40 A.M. direct care staff T said the wireless call light system was up and down and currently it did not function correctly. On 11/13/13 at 11:15 A.M. administrative staff C stated the wireless call light system on Westminster Unit was working. Administrative staff C stated a wire dislodged which caused the call light system not to function. Administrative staff C stated when residents activated the call light, the signal went to the pagers of the direct care staff and the licensed nurse assigned to the unit. Administrative staff C stated if the signal went unanswered for 3 minutes the signal repeated back to the same workstation and to the same staff that received the original call. The facility failed to ensure the wireless call system functioned at all times and also failed to ensure if a signal went unanswered for 3 minutes the signal progressed to another workstation not designated to receive the original call.							

If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATE FORM 021199 W9WZ11 If continuation sheet 4 of 4